

# **INDOOR AIR QUALITY POST-OCCUPANCY ASSESSMENT**

**Commonwealth of Massachusetts  
State Office Building  
21 Spring Street  
Taunton, MA**



Prepared by:  
Massachusetts Department of Public Health  
Bureau of Environmental Health  
Indoor Air Quality Program  
July 2012

## **Background/Introduction**

In response to a request from Bruce Tebo, Project Manager, Division of Capital Asset Management (DCAM), the Massachusetts Department of Public Health (MDPH), Bureau of Environmental Health (BEH) conducted a pre-lease renewal indoor air quality (IAQ) assessment at 21 Spring Street, Taunton, Massachusetts. This evaluation was conducted as part of enhanced efforts to ensure acceptable indoor the air quality of office space leased by Massachusetts state agencies. On May 25, 2012, a visit to conduct a post-occupancy IAQ assessment was made by Cory Holmes, Environmental Analyst/Inspector for BEH's IAQ Program.

The building is a multi-level structure consisting of office space, open work areas and conference/meeting rooms. State tenants have occupied the building for over 20 years and include MassHealth (Office of Medicaid), the Massachusetts Rehabilitation Commission (MRC), the Department of Transitional Assistance (DTA) and the Massachusetts Department of Developmental Services (DDS). Each office space has separate heating, ventilation and air conditioning (HVAC) equipment. Windows are openable in some areas of the building.

## **Methods**

Air tests for carbon monoxide, carbon dioxide, temperature and relative humidity were taken with the TSI, Q-Trak, IAQ Monitor 7565. Air tests for airborne particle matter with a diameter less than 2.5 micrometers were taken with the TSI, DUSTTRAK™ Aerosol Monitor Model 8520. BEH staff also performed visual inspection of building materials for water damage and/or microbial growth and other conditions that may potentially impact IAQ.

## Results

The offices have a combined employee population of approximately 125 with several hundred members of the public conducting business at the offices daily. Test results appear in Table 1 and are listed by function, occupants' last name(s) or office numerical designation (where available).

## Discussion

### Ventilation

It can be seen from Table 1 that carbon dioxide levels were below 800 parts per million (ppm) in all areas tested at the time of assessment, indicating good air exchange throughout the building. Fresh air is provided by rooftop air-handling units (AHUs) (Picture 1). Fresh air is drawn into the AHUs through a bank of high efficiency pleated air filters, heated or cooled and delivered to occupied areas via ducted air diffusers (Picture 2). Return air is drawn into ceiling or wall-mounted vents and ducted back to the rooftop AHUs (Pictures 3 and 4).

The HVAC system is controlled by digital thermostats. Thermostats examined had a fan switch with two settings, *on* and *auto* (Picture 5). When the fan is set to *on*, the system provides a continuous source of air circulation and filtration. The *automatic* setting on the thermostat activates the HVAC system at a preset temperature. Once the preset temperature is reached, the HVAC system is deactivated. Therefore, no mechanical ventilation is provided until the thermostat re-activates the system. The MDPH typically recommends that thermostats be set to the fan *on* setting during occupied hours to provide continuous air circulation. Most of the thermostats throughout the building were set to the fan *on* setting. The thermostat in the MRC

conference room had a “check filter” message indicating, that the filter for that AHU may be in need of changing (Picture 5).

In order to have proper ventilation with a mechanical supply and exhaust system, the systems must be balanced to provide an adequate amount of fresh air to the interior of a room while removing stale air from the room. It is recommended that HVAC systems be re-balanced every five years to ensure adequate air systems function (SMACNA, 1994).

The Massachusetts Building Code requires a minimum ventilation rate of 20 cubic feet per minute (cfm) per occupant of fresh outside air or openable windows (SBBRS, 1997; BOCA, 1993). The ventilation must be on at all times that the room is occupied. Providing adequate fresh air ventilation with open windows and maintaining the temperature in the comfort range during the cold weather season is impractical. Mechanical ventilation is usually required to provide adequate fresh air ventilation.

Carbon dioxide is not a problem in and of itself. It is used as an indicator of the adequacy of the fresh air ventilation. As carbon dioxide levels rise, it indicates that the ventilating system is malfunctioning or the design occupancy of the room is being exceeded. When this happens, a buildup of common indoor air pollutants can occur, leading to discomfort or health complaints. The Occupational Safety and Health Administration (OSHA) standard for carbon dioxide is 5,000 parts per million parts of air (ppm). Workers may be exposed to this level for 40 hours/week, based on a time-weighted average (OSHA, 1997).

The MDPH uses a guideline of 800 ppm for publicly occupied buildings. A guideline of 600 ppm or less is preferred in schools due to the fact that the majority of occupants are young and considered to be a more sensitive population in the evaluation of environmental health status. Inadequate ventilation and/or elevated temperatures are major causes of complaints such

as respiratory, eye, nose and throat irritation, lethargy and headaches. For more information concerning carbon dioxide, please see [Appendix A](#).

Indoor temperatures ranged from 71°F to 77 °F (Table 1), which were within the MDPH recommended comfort range at the time of the assessment. The MDPH recommends that indoor air temperatures be maintained in a range of 70 °F to 78 °F in order to provide for the comfort of building occupants. In many cases concerning indoor air quality, fluctuations of temperature in occupied spaces are typically experienced, even in a building with an adequate fresh air supply.

Relative humidity measurements ranged from 44 to 67 percent (Table 1), which were within or close to the MDPH recommended comfort range in the majority of areas surveyed. The MDPH recommends a comfort range of 40 to 60 percent for indoor air relative humidity. Several building occupants expressed that the building air felt dry. The sensation of dryness and irritation is common in a low relative humidity environment. Low relative humidity is a very common problem during the heating season in the northeast part of the United States.

### **Microbial/Moisture Concerns**

In order for building materials to support mold growth, a source of water exposure is necessary. Water-damaged ceiling tiles were observed in a few areas (Table 1), which indicate current/historic plumbing or roof leaks. Water-damaged ceiling tiles can provide a source of mold and should be replaced after a water leak is discovered and repaired. Occasional leaks were reported by occupants directly inside the 2<sup>nd</sup> floor entrance of the MRC. At the time of the assessment, water-damaged ceiling tiles had been changed. However water-damaged fiberglass insulation located above the ceiling was observed in this area (Picture 6). The US Environmental Protection Agency (US EPA) and the American Conference of Governmental Industrial Hygienists (ACGIH) recommend that porous materials (e.g., carpeting, fiberglass insulation) be

dried with fans and heating within 24 to 48 hours of becoming wet (US EPA, 2001; ACGIH, 1989). If not dried within this time frame, mold growth may occur. Once mold has colonized porous materials, they are difficult to clean and should be removed/discarded.

Plants were observed in several areas. Plants, soil and drip pans can serve as sources of mold/bacterial growth. Plants should be properly maintained, over-watering of plants should be avoided and drip pans should be inspected periodically for mold growth. Mold growth/water damage was observed on shelving in the 2<sup>nd</sup> floor of the MRC as a result of over-watering or leaking drip pans (Picture 7).

Accumulated debris was observed on floor tiles in the MassHealth break room (102) on the 1<sup>st</sup> floor (Picture 8). Occupants and building management could not recall issues with water penetration, therefore it could not be concluded if this material was mastic around floor tiles that had become softened by water infiltration or material stuck to the floor from stored items (e.g., cardboard boxes).

### **Other IAQ Evaluations**

Indoor air quality can be negatively influenced by the presence of respiratory irritants, such as products of combustion. The process of combustion produces a number of pollutants. Common combustion emissions include carbon monoxide, carbon dioxide, water vapor, and smoke (fine airborne particle material). Of these materials, exposure to carbon monoxide and particulate matter with a diameter of 2.5 micrometers ( $\mu\text{m}$ ) or less (PM2.5) can produce immediate, acute health effects upon exposure. To determine whether combustion products were present in the indoor environment, BEH staff obtained measurements for carbon monoxide and PM2.5.

### *Carbon Monoxide*

Carbon monoxide is a by-product of incomplete combustion of organic matter (e.g., gasoline, wood and tobacco). Exposure to carbon monoxide can produce immediate and acute health effects. Several air quality standards have been established to address carbon monoxide and prevent symptoms from exposure to these substances. The MDPH established a corrective action level concerning carbon monoxide in ice skating rinks that use fossil-fueled ice resurfacing equipment. If an operator of an indoor ice rink measures a carbon monoxide level over 30 ppm, taken 20 minutes after resurfacing within a rink, that operator must take actions to reduce carbon monoxide levels (MDPH, 1997).

The American Society of Heating Refrigeration and Air-Conditioning Engineers (ASHRAE) has adopted the National Ambient Air Quality Standards (NAAQS) as one set of criteria for assessing indoor air quality and monitoring of fresh air introduced by HVAC systems (ASHRAE, 1989). The NAAQS are standards established by the US EPA to protect the public health from six criteria pollutants, including carbon monoxide and particulate matter (US EPA, 2006). As recommended by ASHRAE, pollutant levels of fresh air introduced to a building should not exceed the NAAQS levels (ASHRAE, 1989). The NAAQS were adopted by reference in the Building Officials & Code Administrators (BOCA) National Mechanical Code of 1993 (BOCA, 1993), which is now an HVAC standard included in the Massachusetts State Building Code (SBBRS, 1997). According to the NAAQS, carbon monoxide levels in outdoor air should not exceed 9 ppm in an eight-hour average (US EPA, 2006).

*Carbon monoxide should not be present in a typical, indoor environment. If it is present, indoor carbon monoxide levels should be less than or equal to outdoor levels. Outdoor carbon*

monoxide concentrations were non-detect the day of the assessment (Table 1). No measureable levels of carbon monoxide were detected in the building during the assessment (Table 1).

### *Particulate Matter*

The US EPA has established NAAQS limits for exposure to particulate matter. Particulate matter is airborne solids that can be irritating to the eyes, nose and throat. The NAAQS originally established exposure limits to particulate matter with a diameter of 10  $\mu\text{m}$  or less (PM10). According to the NAAQS, PM10 levels should not exceed 150 micrograms per cubic meter ( $\mu\text{g}/\text{m}^3$ ) in a 24-hour average (US EPA, 2006). These standards were adopted by both ASHRAE and BOCA. Since the issuance of the ASHRAE standard and BOCA Code, US EPA established a more protective standard for fine airborne particles. This more stringent PM2.5 standard requires outdoor air particle levels be maintained below 35  $\mu\text{g}/\text{m}^3$  over a 24-hour average (US EPA, 2006). Although both the ASHRAE standard and BOCA Code adopted the PM10 standard for evaluating air quality, MDPH uses the more protective PM2.5 standard for evaluating airborne particulate matter concentrations in the indoor environment.

Outdoor PM2.5 was measured at 12  $\mu\text{g}/\text{m}^3$  (Table 1). PM2.5 levels measured indoors ranged from 7 to 11  $\mu\text{g}/\text{m}^3$  (Table 1), which were below the NAAQS PM2.5 level of 35  $\mu\text{g}/\text{m}^3$ . Frequently, indoor air levels of particulates (including PM2.5) can be at higher levels than those measured outdoors. A number of mechanical devices and/or activities that occur in buildings can generate particulate during normal operations. Sources of indoor airborne particulates may include but are not limited to particles generated during the operation of fan belts in the HVAC system, use of stoves and/or microwave ovens in kitchen areas; use of photocopiers, fax machines and computer printing devices; operation of an ordinary vacuum cleaner and heavy foot traffic indoors.

## **Conclusions/Recommendations**

In view of the findings at the time of the visit, the following recommendations are made:

1. Ensure that all thermostats are set to the fan “on” position to operate the ventilation system continuously in occupied areas during business hours.
2. Change filters for air handling equipment as per the manufacturers’ instructions or more frequently if needed.
3. Adjust HVAC system settings to provide comfort and reduce relative humidity conditions as needed.
4. Ensure roof/plumbing leaks are repaired once discovered. Replace any remaining water-damaged ceiling tiles and fiberglass insulation (e.g., MRC). Monitor for further leaks. If wetting of ceiling tiles recurs, report to building management for prompt remediation.
5. Avoid over watering of plants. Ensure flat surfaces around plants are free of potting soil and other plant debris. Examine drip pans periodically for mold growth and disinfect with an appropriate antimicrobial where necessary. Do not place plants on porous materials (e.g., paper/cardboard).
6. Make repairs/refinish water-damaged shelving in the MRC (Picture 7).
7. Clean black debris from floor tiles in MassHealth break room (102). Monitor for further accumulation and/or water penetration.
8. For buildings in New England, periods of low relative humidity during the winter are often unavoidable. Therefore, scrupulous cleaning practices should be adopted to minimize common indoor air contaminants whose irritant effects can be enhanced when the relative humidity is low. To control for dusts, a high efficiency particulate arrestance (HEPA) filter equipped vacuum cleaner in conjunction with wet wiping of all surfaces is

recommended. Avoid the use of feather dusters. Drinking water during the day can help ease some symptoms associated with a dry environment (throat and sinus irritations).

9. Consider adopting a balancing schedule of every 5 years for all mechanical ventilation systems, as recommended by ventilation industrial standards (SMACNA, 1994).
10. Refer to resource manual and other related indoor air quality documents located on the MDPH's website for further building-wide evaluations and advice on maintaining public buildings. These documents are available at: <http://mass.gov/dph/iaq>.

## References

ACGIH. 1989. Guidelines for the Assessment of Bioaerosols in the Indoor Environment. American Conference of Governmental Industrial Hygienists, Cincinnati, OH.

ASHRAE. 1989. Ventilation for Acceptable Indoor Air Quality. American Society of Heating, Refrigeration and Air Conditioning Engineers. ANSI/ASHRAE 62-1989.

BOCA. 1993. The BOCA National Mechanical Code/1993. 8th ed. Building Officials and Code Administrators International, Inc., Country Club Hill, IL.

MDPH. 1997. Requirements to Maintain Air Quality in Indoor Skating Rinks (State Sanitary Code, Chapter XI). 105 CMR 675.000. Massachusetts Department of Public Health, Boston, MA.

OSHA. 1997. Limits for Air Contaminants. Occupational Safety and Health Administration. Code of Federal Regulations. 29 C.F.R 1910.1000 Table Z-1-A

SBBRS. 1997. Mechanical Ventilation. State Board of Building Regulations and Standards. Code of Massachusetts Regulations. 780 CMR 1209.0

SMACNA. 1994. HVAC Systems Commissioning Manual. 1st ed. Sheet Metal and Air Conditioning Contractors' National Association, Inc., Chantilly, VA.

US EPA. 2001. "Mold Remediation in Schools and Commercial Buildings". Office of Air and Radiation, Indoor Environments Division, Washington, DC. EPA 402-K-01-001. March 2001. Available at: [http://www.epa.gov/iaq/molds/mold\\_remediation.html](http://www.epa.gov/iaq/molds/mold_remediation.html)

US EPA. 2006. National Ambient Air Quality Standards (NAAQS). US Environmental Protection Agency, Office of Air Quality Planning and Standards, Washington, DC. <http://www.epa.gov/air/criteria.html>

**Picture 1**



**One of Several Rooftop Air Handling Units**

**Picture 2**



**Ceiling-Mounted Air Diffuser**

**Picture 3**



**Ceiling-Mounted Return Vent**

**Picture 4**



**Wall-Mounted Return Vent**

**Picture 5**



**Digital Wall Thermostat in MRC Conference Room, Note Fan in *Auto* and *Check Filter* Message**

**Picture 6**



**Water-Damaged Fiberglass Insulation above Ceiling 2<sup>nd</sup> Floor MRC Entrance**

**Picture 7**



**Water-Damaged Shelving near Window 2<sup>nd</sup> Floor MRC**

**Picture 8**



**Accumulated Debris on Floor Tiles in 1<sup>st</sup> Floor MassHealth Break Room (102)**

Location	Carbon Dioxide (*ppm)	Temp (°F)	Relative Humidity (%)	Carbon Monoxide (*ppm)	PM2.5 (µg/m <sup>3</sup> )	Occupants in Room	Windows Openable	Ventilation		
Background	396	72	67	ND	12					Overcast, humid
<b>MA Health</b>										
Reception Area	504	75	60	ND	9	3	N	Y	Y	
101	545	76	57	ND	9	1	N	Y	N	
102 breakroom	511	77	54	ND	9	0	Y	Y	Y	Black material on tile (mastic/water damage?)
103-108	518	77	53	ND	10	1	N	Y	Y	
109-110	501	77	53	ND	8	0	Y	Y	Y	
112-119	503	77	53	ND	8	0	N	Y	Y	
114-117	512	76	52	ND	7	1	N	Y	Y	
120	577	72	50	ND	7	2	Y	Y	Y	DO
126-136	573	75	48	ND	7	4	N	Y	Y	

ppm = parts per million

ND = non detect

WD CT = water-damaged ceiling tiles

µg/m<sup>3</sup> = micrograms per cubic meter

DO = door open

**Comfort Guidelines**

Carbon Dioxide: < 600 ppm = preferred  
 600 - 800 ppm = acceptable  
 > 800 ppm = indicative of ventilation problems

Temperature: 70 - 78 °F  
 Relative Humidity: 40 - 60%

Location	Carbon Dioxide (*ppm)	Temp (°F)	Relative Humidity (%)	Carbon Monoxide (*ppm)	PM2.5 (µg/m <sup>3</sup> )	Occupants in Room	Windows Openable	Ventilation		
127-131	574	73	48	ND	7	3	Y	Y	Y	
132-134	581	74	49	ND	7	2	Y	Y	Y	
138-142	646	73	49	ND	7	2	N	Y	Y	
144	556	74	46	ND	7	0	N	Y	Y	DO
145	603	76	51	ND	7	0	N	Y	N	
200	513	74	55	ND	8	0	Y	Y	Y	Plants
201 Conference Room	390	73	55	ND	9	0	Y	Y	Y	
206	398	73	59	ND	9	1	N	Y	Y	
207	423	73	60	ND	8	0	Y	Y	Y	DO
209-212	421	73	63	ND	8	1	Y	Y	Y	Photocopier
213-221	405	73	62	ND	8	4	N	Y	Y	

ppm = parts per million

ND = non detect

WD CT = water-damaged ceiling tiles

µg/m<sup>3</sup> = micrograms per cubic meter

DO = door open

**Comfort Guidelines**

Carbon Dioxide: < 600 ppm = preferred

600 - 800 ppm = acceptable

> 800 ppm = indicative of ventilation problems

Temperature: 70 - 78 °F

Relative Humidity: 40 - 60%

Location	Carbon Dioxide (*ppm)	Temp (°F)	Relative Humidity (%)	Carbon Monoxide (*ppm)	PM2.5 (µg/m <sup>3</sup> )	Occupants in Room	Windows Openable	Ventilation		
217	415	73	61	ND	8	0	Y	Y	N	
218	447	73	61	ND	8	2	y	Y	N	Plants
227 Training Room	409	73	61	ND	8	0	Y	Y	Y	
231-238	410	73	62	ND	8	2	Y	Y	Y	
239-247	408	74	61	ND	9	3	Y	Y	Y	
248	430	73	61	ND	7	0	Y	Y	Y	
250 Lounge	396	73	59	ND	8	1	N	Y	Y	
251	441	74	55	ND	8	0	Y	Y	Y	DO
<b>MRC</b>										
Reception Area	409	75	56	ND	9	2	N	Y	Y	Photocopier
Callahan	431	74	57	ND	10	1	N	Y	N	DO

ppm = parts per million

ND = non detect

WD CT = water-damaged ceiling tiles

µg/m<sup>3</sup> = micrograms per cubic meter

DO = door open

**Comfort Guidelines**

Carbon Dioxide: < 600 ppm = preferred

600 - 800 ppm = acceptable

> 800 ppm = indicative of ventilation problems

Temperature: 70 - 78 °F

Relative Humidity: 40 - 60%

Table 1 (continued)

Location	Carbon Dioxide (*ppm)	Temp (°F)	Relative Humidity (%)	Carbon Monoxide (*ppm)	PM2.5 (µg/m <sup>3</sup> )	Occupants in Room	Windows Openable	Ventilation		
								Y	N	
Ellis	413	74	57	ND	10	1	N	Y	N	DO
Childers	403	74	57	ND	10	0	N	Y	N	
Olivier	442	74	57	ND	9	1	N	Y	N	DO
Sarkady	503	74	53	ND	9	1	N	Y	N	DO, plants
Silva	493	73	53	ND	9	0	N	Y	N	DO
Ahearn	426	73	53	ND	10	0	N	Y	Y	DO
Tilden	450	73	55	ND	9	1	N	Y	N	DO
Lounge	514	74	58	ND	10	0	N	Y	Y	
Woman's Restroom							N	Y	Y	1 WD CT
Interpreter's Office	406	74	65	ND	11	1	N	Y	N	
Caprio	724	76	51	ND	8	2	N	Y	N	

ppm = parts per million

ND = non detect

WD CT = water-damaged ceiling tiles

µg/m<sup>3</sup> = micrograms per cubic meter

DO = door open

**Comfort Guidelines**

Carbon Dioxide: < 600 ppm = preferred  
 600 - 800 ppm = acceptable  
 > 800 ppm = indicative of ventilation problems

Temperature: 70 - 78 °F  
 Relative Humidity: 40 - 60%

Location	Carbon Dioxide (*ppm)	Temp (°F)	Relative Humidity (%)	Carbon Monoxide (*ppm)	PM2.5 (µg/m <sup>3</sup> )	Occupants in Room	Windows Openable	Ventilation		
Conference Room	553	75	47	ND	7	0	Y	Y	Y	Check filter message on thermostat, fan auto
Rautiainen	546	74	46	ND	9	1	N	Y	N	DO
Monroe	556	74	45	ND	7	1	N	Y	N	DO
Igreja	533	74	45	ND	7	1	N	Y	N	DO
Midura	448	74	44	ND	8	0	Y	Y	N	DO
Cazeau-Class	521	75	46	ND	7	1	Y	Y	N	Plants
Botellho	687	75	47	ND	7	1	N	Y	N	DO
<b>DTA</b>										
Lobby	716	75	67	ND	11	20	N	Y	Y	
Lounge	549	71	57	ND	7	3	N	Y	Y	Plants
Large Conference Room	542	72	57	ND	7	0	N	Y	Y	WD CT-corner

ppm = parts per million

ND = non detect

WD CT = water-damaged ceiling tiles

µg/m<sup>3</sup> = micrograms per cubic meter

DO = door open

**Comfort Guidelines**

Carbon Dioxide: < 600 ppm = preferred

600 - 800 ppm = acceptable

> 800 ppm = indicative of ventilation problems

Temperature: 70 - 78 °F

Relative Humidity: 40 - 60%

Table 1 (continued)

Location	Carbon Dioxide (*ppm)	Temp (°F)	Relative Humidity (%)	Carbon Monoxide (*ppm)	PM2.5 (µg/m <sup>3</sup> )	Occupants in Room	Windows Openable	Ventilation		
Raposo	575	71	53	ND	8	1	N	Y	Y	Plants
Common Work Area (Rear)	603	71	60	ND	8	4	N	Y	Y	
Common Work Area (Center)	617	72	60	ND	9	5	N	Y	Y	
Common Work Area (Center-Right)	639	73	66	ND	9	5	N	Y	Y	
Common Work Area (Maloney)	648	73	67	ND	9	2	N	Y	Y	DO
Common Work Area (Front)	612	73	61	ND	9	6	N	Y	Y	
Reception	706	74	60	ND	9	2	N	Y	Y	
Bertoldo	542	74	60	ND	8	0	N	Y	Y	DO
Computer Lab	375	74	67	ND	9	0	N	Y	Y	Only used periodically, building management contacted to adjust HVAC when in use
<b>DDS</b>										

ppm = parts per million

ND = non detect

WD CT = water-damaged ceiling tiles

µg/m<sup>3</sup> = micrograms per cubic meter

DO = door open

**Comfort Guidelines**

Carbon Dioxide: < 600 ppm = preferred

600 - 800 ppm = acceptable

> 800 ppm = indicative of ventilation problems

Temperature: 70 - 78 °F

Relative Humidity: 40 - 60%

Table 1 (continued)

Location	Carbon Dioxide (*ppm)	Temp (°F)	Relative Humidity (%)	Carbon Monoxide (*ppm)	PM2.5 (µg/m <sup>3</sup> )	Occupants in Room	Windows Openable	Ventilation		
Reception	392	74	61	ND	10	1	N	Y	Y	
Curley	379	73	62	ND	10	0	N	Y	Y	DO
Griffin	402	73	64	ND	10	1	N	Y	N	DO
Voyer	392	73	64	ND	10	0	N	Y	N	DO
Vought	387	73	64	ND	10	0	N	Y	N	
Break Room	456	73	67	ND	10	2	N	Y	N	
Open Work Area (Rear)	413	74	66	ND	10	2	N	Y	Y	
Houston	378	75	65	ND	10	0	N	Y	N	
Conference Room	606	74	64	ND	10	8	N	Y	Y	

ppm = parts per million

ND = non detect

WD CT = water-damaged ceiling tiles

µg/m<sup>3</sup> = micrograms per cubic meter

DO = door open

**Comfort Guidelines**

Carbon Dioxide: < 600 ppm = preferred  
 600 - 800 ppm = acceptable  
 > 800 ppm = indicative of ventilation problems

Temperature: 70 - 78 °F  
 Relative Humidity: 40 - 60%