

780 CMR 54.00 Foundations

With the changes to Chapter 61 the below referenced exception will need to be changed.

5408.2 Opening for under...

Exceptions:

5. Ventilation....are insulated in accordance with 780 CMR ~~6102.1.7~~ **61.00**.